

## VSSW Trade In / Condition Report Ride-On-Trencher/Plow

Date of Inspection: 03/27/2025

Hours: 1,588

Completed by:

S/N#:

Equipment Year / Make / Model: 1997 Tesmec TRS-900SLO

Trencher boom has 38 plates and a total of 54 teeth (Approx digging depth is 6 feet)

	Poor	Fair	Good	v. Good	Exc.
Description	1	2	3	4	5
<b>General Appearance:</b>					
CE Mark Present (check SN# plate) (Y/N)	Y				
Paint Condition					X
Sheet Metal / Fiberglass				X	
Steps / Ladders	NA				
Safety Rails / Hand Rails					X

	Poor	Fair	Good	v. Good	Exc.
Description	1	2	3	4	5
<b>Hydraulics</b>					
Hydraulic Pumps				X	
Hydraulic Motors				X	
Valves				X	
Hoses		X			
Cylinders				X	
Cylinders pins / bushings				X	

<b>Control Station:</b>					
Seats / Armrests					X
Seat Belts	NA				
Hydraulic Controls				X	
Steering Controls				X	
Drivetrain Controls				X	
Oil Pressure				X	
Exterior Lights Operations? (Y/N)	NA				
Engine Warning Lights	NA				
Gauges				X	
Hour Meter / Odometer					X
Limited Function Check Results: (joysticks operations, gauges readable, hour meter functional)					

<b>Trencher Attachment</b>					
Model/SN					
Chain/Sprocket Condition			X		
Pockets/Teeth/Base Plate Condition			X		
Augers/Bearings			X		
Top/Bttom Wear Plates			X		
Sliding Offset Cylinder/Slides if Applicable			X		
End Idler Condition			X		
Crumber/Cylinder/Lock	NA				
Boom Lift Cylinders/Pins			X		
Hose Condition			X		
Attachment Pivot Rings			X		

### VSSW Trade In / Condition Report

<b>Engine:</b>					
Cummins 6CTA 8.3L 260hp					
Diesel					
Emmission Control Label Present? (Y/N)					
Last service dates					
Transmission				X	
blowby, throttle, emergency stop, leaks) New emergency stop and throttle works well					
<b>Backhoe Attachment (If Applicable)</b>					
Model/SN	NA				
Cylinders/Hose Condition	NA				
Bucket Condition	NA				
Outriggers	NA				
<b>Plow Attachment (If Applicable)</b>					
Model/SN	NA				
Blade Condition/ Blade Dimensions	NA				
Shaker Box	NA				
Cylinders/Hoses Condition	NA				

Flashing			X		
Bridge Condition			X		
Boom Length Actual boom is 10 feet long					
Chain Width Tooth Pads 12" wide					
Tooth point to tooth point 14" wide					
<b>Undercarriage:</b>					
Track/Tire/Wheel Condition				X	
Brake Functions	NA				
Axle Condition				X	
Transfer Case (Leaks,Cracks,etc.)				X	
Frame Condition				X	
Backfill Blade/Cylinder/Hoses	NA				
Weight Kit	NA				
<b>Combination Attachments (If Applicable)</b>					
Model/SN	NA				

<p><b>Notes:</b></p> <p>Overall the trencher is very good condition for the year model. Machine was recently professionally painted. All 4 main hydraulic pressure gauges were replaced. Track tilt and cab lift cylinders were all recently rebuilt. Air conditioning works and all of the hoses and dryer were recently replaced. Track pads are all in good shape as are the chain teeth. Operators seat is new and floor was covered with new rubber mat. All functions on the machine work. The crumb show has been removed and several small hydraulic hoses will need to be replaced sooner than later. Machine does not have any oil leaks. Both batteries were recently replaced. Machine will be sold with an extra turbo and exhaust manifold as well as many teeth and wear parts for the boom.</p>	<p><b>Total cost of repairs:</b></p>
---	--------------------------------------