

Date of Inspection: 8/6/24

Completed by:

Equipment Year / Make / Model: Case, SR210 Loader, 2018

	Poor	Fair	Good	v. Good	Exc.
Description	1	2	3	4	5
General Appearance:					
CE Mark Present (check SN# plate) (Y/N)				✓	
Paint Condition				✓	
Sheet Metal / Fiberglass				✓	
Steps / Ladders				✓	
Safety Rails / Hand Rails				✓	
Control Station:					
Seats / Armrests				✓	
Seat Belts				✓	
Hydraulic Controls				✓	
Steering Controls				✓	
Drivetrain Controls				✓	
Oil Pressure				✓	
Exterior Lights Operations? (Y/N)				✓	
Engine Warning Lights				✓	
Gauges				✓	
Hour Meter / Odometer				✓	
Limited Function Check Results: (joysticks operations, gauges readable, hour meter functional)					
Engine:					
Make / Model				✓	
Fuel Type				✓	
Emmission Control Label Present? (Y/N)					

Last service dates	8/6/24						
Transmission					✓		
Limited Function Check Results: (engine start/stop, visual blowby, throttle, emergency stop, leaks)					✓		
Backhoe Attachment (If Applicable)	N/A						
Model/SN							
Cylinders/Hose Condition							
Bucket Condition							
Outriggers							
Plow Attachment (If Applicable)	N/A						
Model/SN							
Blade Condition/ Blade Dimensions							
Shaker Box							
Cylinders/Hoses Condition							
Notes:							

actor

Hours: 5,15

S/N#:

	Poor	Fair	Good	v. Good	Exc.
Description	1	2	3	4	5
Hydraulics					
Hydraulic Pumps				✓	
Hydraulic Motors				✓	
Valves				✓	
Hoses				✓	
Cylinders				✓	
Cylinders pins / bushings				✓	

Trencher Attachment N/A					
Model/SN					
Chain/Sprocket Condition					
Pockets/Teeth/Base Plate Condition					
Augers/Bearings					
Top/Bttom Wear Plates					
Sliding Offset Cylinder/Slides if Applicable					
End Idler Condition					
Crumber/Cylinder/Lock					
Boom Lift Cylinders/Pins					
Hose Condition					
Attachment Pivot Rings					
Flashing					
Bridge Condition					
Boom Length					
Chain Width					

Undercarriage:					
Track/Tire/Wheel Condition				✓	
Brake Functions				✓	
Axle Condition				✓	
Transfer Case (Leaks,Cracks,etc.)				✓	
Frame Condition				✓	
Backfill Blade/Cylinder/Hoses				✓	
Weight Kit				✓	
Combination Attachments (If Applicable)					
Model/SN					

Total cost of repairs:

N/A
